


# Instruction for Intel Flash Tool

Working environment: Windows 7/XP, Intel Core i5-3337U, RAM 4 GB  
Software Version: PhoneFlashTool\_5.2.3.0\_external\_win32.exe

## Flash Tool Installation:

1. download the software for Intel device.




Here, the file name is “Intel windows Flash Tool.zip”. Unzip this file. Click into folder and here is “PhoneFlashTool\_5.2.3.0\_external\_win32.exe”. Install this software. It will create an icon on your desktop.



## Flash image:

Open the software and the window is showed below. Following the 2 steps which have already been showed in the red rectangle.




2.1 Unzip your image, browse the “flash\*.xml” (Here is flash5.1 userdebug.xml).

`\images_flash_cube_i10_r1-B2016040501-signed\images_flash_cube_i10_r1-B2016040501\flash5.1_userdebug.xml`

2.2 Connect device with computer through USB. The computer will detect your device automatically. The screen will show up the “Start to flash” button(Here is in the rectangle 2). Press this button.

2.3 There is a process bar on the right.



2.4 It will show “Flash success” on the right.

